

Lab Sr. no.	Date	Received through Email/Phone No	Daily Sr No.	Source	Sodium Thiosulphate	MPN	Final report (72Hrs)	FINAL REPORTING DATE	Result
3965	08-07-2019	Samples received from Assistant Engineer, Shimla Jal Prabandhan Nigam Ltd	1	Kasumpti Reservoir	added	MPN=0	thermotolerant E.coli not detected	08-10-2019	excellent
3966			2	Sector-2 tank (repeat)	added	MPN=0	thermotolerant E.coli not detected	08-10-2019	excellent
3967			3	Bhimakali tank (repeat)	added	MPN=0	thermotolerant E.coli not detected	08-10-2019	excellent
3968			4	Yadgar tank (repeat)	added	MPN=0	thermotolerant E.coli not detected	08-10-2019	excellent
3969			5	Public tank near Yadgar(repeat)	added	MPN=0	thermotolerant E.coli not detected	08-10-2019	excellent
3970			6	Public tap near Totu chowk(repeat)	added	MPN=0	thermotolerant E.coli not detected	08-10-2019	excellent
3971			7	Public tap near Gupta pan house Totu(repeat)	added	MPN=0	thermotolerant E.coli not detected	08-10-2019	excellent
3972			8	Sanjauli reservoir	added	MPN=4	thermotolerant E.coli not detected	08-10-2019	SUSPICIOUS
3973	08-07-2019	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	Ridge tank	added	MPN=0		08-09-2019	excellent
3974			2	Mains field tank	added	MPN=1		08-09-2019	
3975			3	Snowdone pump house inlet	added	MPN=0		08-09-2019	excellent
3976			4	Dhalli tank	added	MPN=18		08-09-2019	unsatisfactory
3977			5	Tavi tank	added	MPN=0		08-09-2019	excellent
3978			6	Near IPH controle room ridge	added	MPN=0		08-09-2019	excellent
3979			7	jakhoo ropeway tank	added	MPN=0		08-09-2019	excellent

3980			8	Pub-tap brock host chotta Shimla	added	MPN=0		08-09-2019	excellent
3981			9	Pub-tap near samsung show room the mall	added	MPN=30		08-09-2019	Unsatisfactory
3982			10	Pub-tap near khadi aashram the mall	added	MPN=1		08-09-2019	
3983			11	Pub-tap nearCTO the mall	added	MPN=0		08-09-2019	excellent
3984			12	Pub-tap near HPMC Ridge	added	MPN=0		08-09-2019	excellent