

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
216	19-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P.)	1	Sanjauli Reservoir Outlet	-	Added	0	-	21-Mar	Excellent
217			2	Sanjauli Inlet Guma	-	Added	0	-	21-Mar	Excellent
218			3	Sanjauli Inlet Giri	-	Added	0	-	21-Mar	Excellent
219			4	North Oak (O.H)	-	Added	0	-	21-Mar	Excellent
220			5	Kasumpti Reservoir	-	Added	0	-	21-Jan	Excellent
221			6	Ridge	-	Added	0	-	21-Mar	Excellent
222	20-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P.)	1	Sanjauli Inlet Guma	-	Added	In Process			
223			2	Sanjauli Inlet Giri	-	Added	11	-	22-Mar	unsatisfactory
224			3	North Oak (O.H)	-	Added	0	-	22-Mar	Excellent
225			4	Enginee Ghar	-	Added	0	-	22-Mar	Excellent
226			5	Kasumpti Reservoir	-	Added	0	-	22-Mar	Excellent
227			6	Phase III sub697	-	Added	0	-	22-Mar	Excellent

228	21-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Sanjauli Inlet Guma	-	Added	In Process
229			2	Sanjauli Inlet Giri	-	Added	In Process
230			3	Sanjauli Resevior outlet	-	Added	In Process
231			4	Sanjauli Chowk Public Tap	-	Added	In Process
232			5	Bangala Colony public Tapwater	-	Added	In Process
233			6	Keleston Tank	-	Added	In Process
234	22-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Kasumpti Reservoir	-	Added	In Process
235			2	Vikas nagar public Tap	-	Added	In Process
236			3	Sanjauli Inlet Guma	-	Added	In Process
237			4	Sanjauli Inlet Giri	-	Added	In Process
238			5	Sanjauli resevior	-	Added	In Process
239			6	Ridge Tap water	-	Added	In Process

240	22-Mar	BMOmashobra	7	pump house shrula under water scheme malyana sample 1	-	Added	In Process
241			8	pump house shrula under water scheme malyana sample 2 raw water	-	Added	In Process