

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
248	24-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	power House main Tank	-	Added	0	-	26-Mar	Excellent
249			2	Lower chakkar main Tank	-	Added	0	-	26-Mar	Excellent
250			3	main tank kasumpti	-	Added	0	-	26-Mar	Excellent
251			4	Giri outlet main line	-	Added	0	-	26-Mar	Excellent
252			5	Guma main line out let	-	Added	0	-	26-Mar	Excellent
253			6	sanjauli main reservior tank	-	Added	0	-	26-Mar	Excellent
254	25-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	baluganj chowk tank	-	Added			In Process	
255			2	summer hill tank	-	Added			In Process	
256			3	kasumpti main tank	-	Added			In Process	
257			4	Sanjauli Inlet Giri	-	Added			In Process	

258			5	Sanjauli Inlet Guma	-	Added	In Process
259			6	Sanjauli reservior outlet main tank	-	Added	In Process
260	26-Mar	Samples received from Corporate Health Officer, Muni- cipal Corporation Shimla, Shimla( H.P)	1	churat outlet	-	Added	In Process
261			2	dingoo main tank sanjauli	-	Added	In Process
262			3	Kaumpti Tank	-	Added	In Process
263			4	Giri outlet main line	-	Added	In Process
264			5	Guma main line out let	-	Added	In Process
265			6	Sanjauli reservior outlet main tank	-	Added	In Process
266			7	naldera area inlet	-	Added	In Process
267			8	naldera area outlet	-	Added	In Process