Water samples tested in Department of Microbiology IGMC, Shimla											
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result	
268	27-Mar	Samples received from Corporate Health Officer,Municipal Corporation Shimla,Shimla(H.P)	1	kasumpti main tank	-	Added	0		29-Mar	Excellent	
269			2	SDAcomple main tank kasumpti	-	Added	0	-	29-Mar	Excellent	
270			3	main tank raj bhavan chota shimla	-	Added	0	-	29-Mar	Excellent	
271			4	Giri inlet	-	Added	0	-	29-Mar	Excellent	
272			5	Guma in let	-	Added	0	-	29-Mar	Excellent	
273			6	Sanjauli reservior outlet main tank	-	Added	0	-	29-Mar	Excellent	
274	28-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Ridge main tank	-	Added		In	Process		
275			2	103 Main Tank Tutukandi	-	Added		In	Process		
276			3	kasumpti main tank	-	Added		In	Process		
277			4	Giri inlet	-	Added	In Process				
278			5	Guma inlet Sanjauli	-	Added		In	Process		
279			6	Sanjauli reservior outlet main tank	-	Added		In	Process		
280	29-Mar	Samples received from Corporate Health Officer,Municipal Corporation Shimla,Shimla(H.P)	1	jakhoo lower Tank(underground)	-	Added		In	Process		
281			2	upper main tank jakhoo	-	Added		In	Process		

282		3	kasumpti main tank	-	Added	In Process
283		4	Giri inlet	-	Added	In Process
284		5	Guma inlet Sanjauli	-	Added	In Process
285		6	Sanjauli reservior outlet main tank	-	Added	In Process