

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
274	28-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Ridge main tank	-	Added	0	-	30-Mar	Excellent
275			2	103 Main Tank Tutukandi	-	Added	0	-	30-Mar	Excellent
276			3	kasumpti main tank	-	Added	0	-	30-Mar	Excellent
277			4	Giri inlet	-	Added	0	-	30-Mar	Excellent
278			5	Guma inlet Sanjauli	-	Added	0	-	30-Mar	Excellent
279			6	Sanjauli reservoir outlet main tank	-	Added	0	-	30-Mar	Excellent
280	29-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	jakhoo lower Tank (underground)	-	Added				In Process
281			2	upper main tank jakhoo	-	Added				In Process
282			3	kasumpti main tank	-	Added				In Process
283			4	Giri inlet	-	Added				In Process
284			5	Guma inlet Sanjauli	-	Added				In Process
285			6	Sanjauli reservoir outlet main tank	-	Added				In Process
286	30-Mar	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Main tank 103 Fagli Ram Nagar	-	Added				In Process
287			2	Nolswood Main tank Chotta Shimla	-	Added				In Process

288			3	kasumpti main tank	-	Added	In Process
289			4	Giri inlet	-	Added	In Process
290			5	Guma inlet Sanjauli	-	Added	In Process