

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
505	2-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	ridge tank (outlet shiv mandir)	-	Added	0	-	04-May	Excellent
506			2	Public Tap Khalini Chowk	-	Added	0	-	04-May	Excellent
507			3	main tank phase III Kagnadhar	-	Added	0	-	04-May	Excellent
508			4	main tank kasumpti	-	Added	0	-	04-May	Excellent
509			5	sanjauli inlet guma	-	Added	0	-	04-May	Excellent
510			6	sanjauli inlet giri	-	Added	0	-	04-May	Excellent
511			7	main mashobra tank	-	Added	0	-	04-May	Excellent
512	3-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	Ridge main tank	-	Added	In Process			
513			2	main tank kasumpti	-	Added	In Process			
514			3	main tank dingu mandir	-	Added	In Process			
515			4	ddhalli filter	-	Added	In Process			
516			5	main tank reservoir sanjauli outlet	-	Added	In Process			
517			6	sanjauli inlet guma	-	Added	In Process			
518			7	sanjauli inlet giri	-	Added	In Process			

519	4-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank ridge	-	Added	In Process
520			2	main tank kasumpti	-	Added	In Process
521			3	Main tank Engine ghar	-	Added	In Process
522			4	main tank reservior sanjauli outlet	-	Added	In Process
523			5	sanjauli inlet guma	-	Added	In Process
524			6	sanjauli inlet giri	-	Added	In Process