

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
539	7-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added	0	-	09-May	Excellent
540			2	main tank bharari	-	Added	0	-	09-May	Excellent
541			3	main tank kalston	-	Added	0	-	09-May	Excellent
542			4	main tank kasumpti	-	Added	0	-	09-May	Excellent
543			5	main tank reservoir sanjauli	-	Added	0	-	09-May	Excellent
544			6	sanjauli inlet guma	-	Added	0	-	09-May	Excellent
545			7	sanjauli inlet giri	-	Added	0	-	09-May	Excellent
546	8-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge main tank	-	Added				In Process
547			2	chotta tank Fhingas	-	Added				In Process
548			3	badha tank Fhingas	-	Added				In Process
549			4	main tank kasumpti	-	Added				In Process
550			5	sanjauli inlet guma(inlet)	-	Added				In Process
551			6	sanjauli inlet giri(inlet)	-	Added				In Process
552	9-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	ridge(outlet)	-	Added				In Process

553			2	public tank near laxmi narayan mandir chotta shimla	-	Added	In Process
554			3	public tapnkasumpti chowk	-	Added	In Process
555			4	main tank kasumpti	-	Added	In Process
556			5	main tank reservior sanjauli	-	Added	In Process
557			6	sanjauli inlet guma(inlet)	-	Added	In Process
558			7	sanjauli inlet giri(inlet)	-	Added	In Process