

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
635	23-May		2	main tank sanskriti collage fagli	-	Added	14	-	26-May	unsatisfactory
641	24-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank kasumpti	-	Added	0	-	26-May	Excellent
642			2	public tap laxmi narayan mandirkasumpti	-	Added	0	-	26-May	Excellent
643			3	main tank woodvilla hotel side mains field tank no1	-	Added	0	-	26-May	Excellent
644			4	main tank raj bhawan side main field tank no 2	-	Added	0	-	26-May	Excellent
645			5	main tank reservoir sanjauli	-	Added	0	-	26-May	Excellent
646			6	sanjauli inlet guma(inlet)	-	Added	0	-	26-May	Excellent
647			7	sanjauli inlet giri(inlet)	-	Added	180	-		unsatisfactory
648	25-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	summerhill road below adwans study main tank	-	Added	In Process			
649			2	tap water summerhill chowk	-	Added	In Process			
650			3	public tap summer hill bazar	-	Added	In Process			
651			4	maun tank summer hill bazar	-	Added	In Process			
652			5	reservoir sanjauli outlet	-	Added	In Process			

653			6	sanjauli inlet guma(inlet)	-	Added	In Process
654			7	sanjauli inlet giri(inlet)	-	Added	In Process
655	26-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank kasumpti	-	Added	In Process
656			2	main tank rani ground basant vihar	-	Added	In Process
657			3	public tap lower panthaghati near bhatiya niwas	-	Added	In Process
658			4	main tank underground IAS colony sargin no1	-	Added	In Process
659			5	main tank IAS colony sargin no 2	-	Added	In Process
660			6	reservior sanjauli outlet	-	Added	In Process
661			7	sanjauli inlet guma(inlet)	-	Added	In Process