

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
648	25-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	summerhill road below adwans study main tank	-	Added	0	-	27-May	Excellent
649			2	tap water summerhill chowk	-	Added	0	-	27-May	Excellent
650			3	public tap summer hill bazar	-	Added	0	-	27-May	Excellent
651			4	maun tank summer hill bazar	-	Added	0	-	27-May	Excellent
652			5	reservior sanjauli outlet	-	Added	0	-	27-May	Excellent
653			6	sanjauli inlet guma(inlet)	-	Added	0	-	27-May	Excellent
654			7	sanjauli inlet giri(inlet)	-	Added	0	-	27-May	Excellent
655	26-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla (H.P)	1	main tank kasumpti	-	Added				In Process
656			2	main tank rani ground basant vihar	-	Added				In Process
657			3	public tap lower panthaghati near bhatiya niwas	-	Added				In Process
658			4	main tank underground IAS colony sargin no1	-	Added				In Process
659			5	main tank IAS colony sargin no 2	-	Added				In Process

660			6	reservior sanjauli outlet	-	Added	In Process
661			7	sanjauli inlet guma(inlet)	-	Added	In Process
662	27-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank kasumpti	-	Added	In Process
663			2	main tank phase III near block 6,7 kagna dhar	-	Added	In Process
664			3	shiv mandir bouri sector 5 phase III kagna dhar	-	Added	In Process
665			4	Sh Beli Ram Aman Kanj (kitchen) phASE iii scctor56 kagna dhar	-	Added	In Process
666			5	Sh Ashok Sharma sharma niwas(kitchen) sector 5	-	Added	In Process
667			6	Smt shasho sani set no II (Kitchen)block no 20 sector 5 kagna dhar	-	Added	In Process
668			7	Sh Kamal Arora (Tanki) sectro 6 block no 5 phase III BCS	-	Added	In Process
669			8	reservior sanjauli outlet	-	Added	In Process