

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
705		samples received from office of block medical officer chirgaon distt shimla	8	CHC chrgaon PHC diudi Tap water 1	-	Added	25	-	4-Jun	unsatisfactory
706			9	Sub Centre janglikh Village Janglikh Tap water 2	-	Added	180	-	4-Jun	unsatisfactory
707	2-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Mains field out let	-	Added	0	-	4-Jun	Excellent
708			2	Kasumpti reserivior	-	Added	0	-	4-Jun	Excellent
709			3	kalyani tank	-	Added	0	-	4-Jun	Excellent
710			4	jaungla tank	-	Added	0	-	4-Jun	Excellent
711			5	retreat (kitchen)	-	Added	0	-	4-Jun	Excellent
712			6	sanjauli inlet gumma	-	Added	0	-	4-Jun	Excellent
713			7	sanjauli inlet giri	-	Added	0	-	4-Jun	Excellent
714			8	sanjauli reserivior outlet	-	Added	0	-	4-Jun	Excellent

715	3-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	retreat (kitchen)	-	Added	In Process
716			2	jaungla tank	-	Added	In Process
717			3	kalyani tank	-	Added	In Process
718			4	craigneno tank	-	Added	In Process
719			5	reservior sanjauli outlet	-	Added	In Process
720			6	sanjauli inlet guma(inlet)	-	Added	In Process
721			7	giri line inlet sanjauli	-	Added	In Process
722			8	Kasumpti reservior	-	Added	In Process
723	4-Jun	Samples received from Corporate Health Officer, Municipal	1	Ridge tap water	-	Added	In Process
724			2	HP07A 0661 MC tanker	-	Added	In Process
725			3	retreat (kitchen)	-	Added	In Process
726			4	jangla tank	-	Added	In Process
727			5	kalyani tank	-	Added	In Process
728			6	sanjauli reservior outlet	-	Added	In Process
729			7	giri line inlet sanjauli	-	Added	In Process
730			8	Kasumpti reservior	-	Added	In Process