

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
723	4-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge tap water	-	Added	0	-	6-Jun	Excellent
724			2	HP07A 0661 MC tanker	-	Added	0	-	6-Jun	Excellent
725			3	retreat (kitchen)	-	Added	0	-	6-Jun	Excellent
726			4	jangla tank	-	Added	0	-	6-Jun	Excellent
727			5	kalyani tank	-	Added	0	-	6-Jun	Excellent
728			6	sanjauli reservior outlet	-	Added	0	-	6-Jun	Excellent
729			7	giri line inlet sanjauli	-	Added	0	-	6-Jun	Excellent
730			8	Kasumpti reservior	-	Added	0	-	6-Jun	Excellent
731	5-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Ridge tap water	-	Added	In Process			
732			2	retreat (kitchen)	-	Added	In Process			
733			3	jaungla tank	-	Added	In Process			
734			4	kalyani tank	-	Added	In Process			
735			5	sanjauli reservior outlet	-	Added	In Process			

736			6	sanjauli inlet gumma	-	Added	In Process
737			7	giri line inlet sanjauli	-	Added	In Process
738			8	Kasumpti reservior	-	Added	In Process
739	6-Jun		1	retreat (kitchen)	-	Added	In Process
740			2	jaungla tank	-	Added	In Process
741			3	kalyani tank	-	Added	In Process
742			4	sanjauli reservior outlet	-	Added	In Process
743			5	sanjauli inlet gumma	-	Added	In Process
744			6	giri line inlet sanjauli	-	Added	In Process
745			7	Kasumpti reservior	-	Added	In Process
746			8	ridge	-	Added	In Process