

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
813	16-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	bhairi lal building public tap annadale	-	Added	0	-	18-Jun	Excellent
814			2	kaithu chowk public tap	-	Added	0	-	18-Jun	Excellent
815			3	dhubi ghatt annadale public tap	-	Added	0	-	18-Jun	Excellent
816			4	tara hall tank	-	Added	12	-	18-Jun	unsatisfactory
817			5	kamana devi tank	-	Added	0	-	18-Jun	Excellent
818			6	sanjauli reservoir out let	-	Added	0	-	18-Jun	Excellent
819			7	kasumpti resrvior	-	Added	0	-	18-Jun	Excellent
820	17-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	tara mata mandir tank	-	Added	In Process			
821			2	Phase III Tank near Block 6,7	-	Added	In Process			
822			3	public tap vikas nagar	-	Added	In Process			
823			4	vikas nagar near C 41 tank	-	Added	In Process			
824			5	kasumpti resrvior	-	Added	In Process			
825			6	sakrala near type IV tank	-	Added	In Process			

826			7	sanjauli reservoir out let	-	Added	In Process
827	18-Jun	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	dingoo mandir tank	-	Added	In Process
828			2	north oak tank(OH)	-	Added	In Process
829			3	north oak tank(gg)	-	Added	In Process
830			4	sanjauli reservoir out let	-	Added	In Process
831			5	engine ghar tank	-	Added	In Process
832			6	kasumpti resrvior	-	Added	In Process