

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	DCC	Reported on	Result
684	29-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank kasumpti	-	Added	0	-	1-Jun	Excellent
685			2	main tank kalyani heli pad chharabra	-	Added	0	-	1-Jun	Excellent
686			3	retreat (kitchen)	-	Added	0	-	1-Jun	Excellent
687			4	pump house mashobra	-	Added	0	-	1-Jun	Excellent
688			5	sanjauli inlet guma(inlet)	-	Added	0	-	1-Jun	Excellent
689			6	giri line inlet sanjauli	-	Added	0	-	1-Jun	Excellent
690			7	reservior sanjauli outlet	-	Added	0	-	1-Jun	Excellent
691	25-May	Samples received from Corporate Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	main tank ridge outlet shiv mandir	-	Added	In Process			
692			2	public tap near pump house lakkar bazar	-	Added	In Process			
693			3	main tank kalyani heli pad chharabra	-	Added	In Process			
694			4	retreat (kitchen)	-	Added	In Process			
695			5	sanjauli inlet guma(inlet)	-	Added	In Process			
696			6	giri line inlet sanjauli	-	Added	In Process			

697			7	giri line inlet sanjauli	-	Added	In Process
698			1	kamal Arora set 6 block no 5	-	Added	In Process
699			2	Kasumpti reservior	-	Added	In Process
700			3	kalyani tank	-	Added	In Process
701			4	retreat (kitchen)	-	Added	In Process
702			5	sanjauli inlet guma(inlet)	-	Added	In Process
703			6	giri line inlet sanjauli	-	Added	In Process
704			7	reservior sanjauli outlet	-	Added	In Process
705		samples received from office of block medical officer chirgaon distt shimla	8	CHC chrgaon PHC diudi Sub Centre janglikh Village Janglikh Tap water 1	-	Added	In Process
706			9	CHC chrgaon PHC diudi Sub Centre janglikh Village Janglikh Tap water 2	-	Added	In Process