Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulph ate	PCC	DCC	Reported on	Result
3198	8-Jul	Samples received from Corporation Health Officer,Municipal Corporation Shimla,Shimla(H.P)	1	public tap bhiari lala building annadale	1	added	0		10-Jul	Excellent
3199			2	hand pump bhiari lal building	-	added	0			Excellent
3200			3	public tap govt school annadale	-	added	0			Excellent
3201			4	Tara Hall Tank	-	added	0			Excellent
3202			5	nitin chauhan snow view borwell	-	added	0			Excellent
3203			6	sanjauli reservior outlet	-	added	0			Excellent
3204			7	kasumpti reservior	-	added	0			Excellent
3205	9-Jul	Samples received from Corporation Health Officer,Municipal Corporation Shimla,Shimla(H.P)	1	sanjauli reservior outlet	1	added	0	-	11-Jul	Excellent
3206			2	kasumpti reservior	-	added	0	-		Excellent
3207			3	SDA complex kasumpti tank	-	added	0	-		Excellent
3208			4	public tap durga cottage SDA complex	-	added	0	-		Excellent
3209			5	Block C-41 Vikas Nagar Tank	-	added	0	-		Excellent
3210			6	block A1 vikas nagar public tap	-	added	0	-		Excellent