

Water samples tested in Department of Microbiology IGMC, Shimla

| Lab Sr. no. | Date | Received through Email/Phone No. | Daily Sr No. | Source | Site | Na thiosulphate | PCC | DCC | Reported on | Result |
|-------------|-------|---|--------------|---|------|-----------------|-------|-----|-------------|----------------|
| 3391 | 8-Aug | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | main tank kasumpti | - | added | 0 | - | 10-Aug | excellent |
| 3392 | | | 2 | main tank I.A.S colonysargrin | - | added | 0 | - | 10-Aug | excellent |
| 3393 | | | 3 | main tank parvati niwas sargrin | - | added | 0 | - | 10-Aug | excellent |
| 3394 | | | 4 | main tank electricity power office pantaghati | - | added | 0 | - | 10-Aug | excellent |
| 3395 | | | 5 | main supply prabhuram sharma niwas upper pantaghati | - | added | MPN11 | | 11-Aug | unsatisfactory |
| 3396 | | | 6 | teser waix snjauli outlet | - | added | 0 | - | 10-Aug | excellent |
| 3397 | 9-Aug | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | main tank tara hall | - | added | 0 | - | 11-Aug | EXCELLENT |
| 3398 | | | 2 | public tap lower kaithu bazar | - | added | 0 | - | 11-Aug | Excellent |
| 3399 | | | 3 | public tap metha niwas lower kaithu | - | added | MPN1 | | 11-Aug | satisfactory |
| 3400 | | | 4 | public tap upper kaithu bazar | - | added | 0 | - | 11-Aug | Excellent |
| 3401 | | | 5 | main tank kasumpti | - | added | 0 | - | 11-Aug | Excellent |