

| Water samples tested in Department of Microbiology IGMC, Shimla | | | | | | | | | | |
|---|--------|---|--------------|---|------|------------------|-----|----------------------|-------------|-----------|
| Lab Sr. no. | Date | Received through Email/Phone No. | Daily Sr No. | Source | Site | Na thiosulph ate | PCC | Final report (72Hrs) | Reported on | Result |
| 4430 | 11-Jan | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | Public Tap Mehlee Chow Kasumpti | - | added | 0 | - | 13-Jan | Excellent |
| 4431 | | | 2 | Water Tap SSB Training Center Kasumpti | - | added | 0 | - | 13-Jan | Excellent |
| 4432 | | | 3 | Water Tank Rani Ground Kasumpti | - | added | 0 | - | 13-Jan | Excellent |
| 4433 | | | 4 | Water Tank Sakrala Kasumpti | - | added | 0 | - | 13-Jan | Excellent |
| 4434 | | | 5 | Water Tank Kasumpti | - | added | 0 | - | 13-Jan | Excellent |
| 4435 | | | 6 | Public Tap Bakhora Niwas, The Mall Shimla | - | added | 0 | - | 13-Jan | Excellent |
| 4436 | | | 7 | Sanjauli Reservoir Outlet | - | added | 0 | - | 13-Jan | Excellent |
| 4437 | 12-Jan | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | public tap indira chowk lower bazar | - | added | 0 | - | 14-Jan | Excellent |
| 4438 | | | 2 | Public Tap Near Tunnel Lower Bazar | - | added | 0 | - | 14-Jan | Excellent |
| 4439 | | | 3 | Public Tap Ganj bazar | - | added | 0 | - | 14-Jan | Excellent |
| 4440 | | | 4 | Public Tap DDU Hospital | - | added | 0 | - | 14-Jan | Excellent |
| 4441 | | | 5 | public tap cart road | - | added | 0 | - | 14-Jan | Excellent |
| 4442 | | | 6 | Water Tank Kasumpti | - | added | 0 | - | 14-Jan | Excellent |
| 4443 | | | 7 | Sanjauli Reservoir Outlet | - | added | 0 | - | 14-Jan | Excellent |
| 4444 | 13-Jan | Samples received from Corporation Health Officer, | 1 | Water tank Engine ghar | - | added | 0 | - | 15-Jan | Excellent |
| 4445 | | | 2 | Water tank Bangala colony | - | added | 0 | - | 15-Jan | Excellent |
| 4446 | | | 3 | Water Tank Kasumpti | - | added | 0 | - | 15-Jan | Excellent |
| 4447 | | | 4 | Public tap power house Malyana | - | added | 0 | - | 15-Jan | Excellent |
| 4448 | | | 5 | Water tank upper housing board colony I | - | added | 0 | - | 15-Jan | Excellent |
| 4449 | | | 6 | Water tank lower housing board colonyII | - | added | 0 | - | 15-Jan | Excellent |
| 4450 | | | 7 | Sanjauli Reservoir Outlet | - | added | 0 | - | 15-Jan | Excellent |

| | | | | | | | | | | |
|------|--------|---|---|--|---|-------|---|---|--------|-----------|
| 4451 | 14-Jan | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | water tank upper (1) dingu mandir | - | added | 0 | - | 16-Jan | Excellent |
| 4452 | | | 2 | water tank lower (2) dingu mandir | - | added | 0 | - | 16-Jan | Excellent |
| 4453 | | | 3 | public tap (R) geol appartment dingu dhar | - | added | 0 | - | 16-Jan | Excellent |
| 4454 | | | 4 | public tap (L) geol appartment dingu dhar | - | added | 0 | - | 16-Jan | Excellent |
| 4455 | | | 5 | pump house dhali dingu mandir | - | added | 0 | - | 16-Jan | Excellent |
| 4456 | | | 6 | sanjauli reserrior outlet | - | added | 0 | - | 16-Jan | Excellent |
| 4457 | | | 7 | water tank kasumpti | - | added | 0 | - | 16-Jan | Excellent |
| 4458 | 15-Jan | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | Water ATM Ridge | - | added | 0 | - | 17-Jan | Excellent |
| 4459 | | | 2 | Water tank Ridge outlet Shiv Mandir Middle Bazar | - | added | 0 | - | 17-Jan | Excellent |
| 4460 | | | 3 | Public tap Ram mandir Ram Bazar | - | added | 0 | - | 17-Jan | Excellent |
| 4461 | | | 4 | Public tap Chota Shimla Chowk | - | added | 0 | - | 17-Jan | Excellent |
| 4462 | | | 5 | Water ATM Vikas Nagar | - | added | 0 | - | 17-Jan | Excellent |
| 4463 | | | 6 | Water tank Kasumpti | - | added | 0 | - | 17-Jan | Excellent |
| 4464 | | | 7 | Sanjauli Reservoir outlet | - | added | 0 | - | 17-Jan | Excellent |
| 4465 | 16-Jan | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | Public tap Five Bench Jakhu | - | added | 0 | - | 18-Jan | Excellent |
| 4466 | | | 2 | Water tank Upper Jakhu Mandir | - | added | 0 | - | 18-Jan | Excellent |
| 4467 | | | 3 | Water tank Lower Jakhu Mandir | - | added | 0 | - | 18-Jan | Excellent |
| 4468 | | | 4 | Water tank Kasumpti | - | added | 0 | - | 18-Jan | Excellent |
| 4469 | | | 5 | Water tank OH North Oak | - | added | 0 | - | 18-Jan | Excellent |
| 4470 | | | 6 | Water tank U. ground North Oak | - | added | 0 | - | 18-Jan | Excellent |
| 4471 | | | 7 | Sanjauli reservoir outlet | - | added | 0 | - | 18-Jan | Excellent |

| | | | | | | | | | | |
|------|--------|---|---|--|---|-------|---|---|--------|--------------|
| 4472 | 17-Jan | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | water tank kasumpti | - | added | 0 | - | 19-Jan | Excellent |
| 4473 | | | 2 | Water Tank Sakrala Kasumpti | - | added | 0 | - | 19-Jan | Excellent |
| 4474 | | | 3 | Water Tank IPH Rani Ground Basant Vihar Kasumpti | - | added | 0 | - | 19-Jan | Excellent |
| 4475 | | | 4 | Water Tank Rani Ground Basant Vihar Kasumpti | - | added | 0 | - | 19-Jan | Excellent |
| 4476 | | | 5 | Water Tank PWD Police Colony Basant Vihar Kasumpti | - | added | 0 | - | 19-Jan | Excellent |
| 4477 | | | 6 | Water Tank IPH supply Basant Vihar Kasumpti | - | added | 1 | - | 20-Jan | satisfactory |
| 4478 | | | 7 | Sanjauli Reservoir out let | - | added | 0 | - | 20-Jan | Excellent |
| 4479 | 18-Jan | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | public tap meat shop Eadgha Ruddhow bhotta | - | added | 0 | - | 20-Jan | Excellent |
| 4480 | | | 2 | public tap krishan cottage Ruddhow | - | added | 0 | - | 20-Jan | Excellent |
| 4481 | | | 3 | public tap lakkar bazar chowk | - | added | 0 | - | 20-Jan | Excellent |
| 4482 | | | 4 | pump house IGMC Road lakkar bazar | - | added | 0 | - | 20-Jan | Excellent |
| 4483 | | | 5 | public tap IGMC | - | added | 0 | - | 20-Jan | Excellent |
| 4484 | | | 6 | water tank kasumpti | - | added | 0 | - | 20-Jan | Excellent |
| 4485 | | | 7 | Sanjauli Reservoir out let | - | added | 0 | - | 20-Jan | Excellent |
| 4486 | 19-Jan | Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P) | 1 | Water tank Kasumpti | - | added | 0 | - | 21-Jan | Excellent |
| 4487 | | | 2 | Public tap Dhalli bazar | - | added | 0 | - | 21-Jan | Excellent |
| 4488 | | | 3 | Dhalli filter | - | added | 0 | - | 21-Jan | Excellent |
| 4489 | | | 4 | Water tank Mashobra | - | added | 0 | - | 21-Jan | Excellent |
| 4490 | | | 5 | Public tap Kapoor vaishno bhojnalya Mashobra bazar | - | added | 0 | - | 21-Jan | Excellent |
| 4491 | | | 6 | Public tap New Msahobra II bazar | - | added | 0 | - | 21-Jan | Excellent |
| 4492 | | | 7 | Sanjauli reservoir outlet | - | added | 0 | - | 21-Jan | Excellent |