

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	Final report (72Hrs)	Reported on	Result
795	4-May	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	tap water verma building 1st floor kuftadhar	-	added	0	-	6-May	Excellent
796			2	tap water verma building II nd floor kuftadhar	-	added	0	-	6-May	Excellent
797			3	tap water ram saran building kuftadhar	-	added	0	-	6-May	Excellent
798			4	tap water manohar lal building kuftadhar	-	added	0	-	6-May	Excellent
799			5	Bharari Tank	-	added	0	-	6-May	Excellent
800			6	sanjauli reservior outlet	-	added	0	-	6-May	Excellent
801			7	kasumpti reservior outlet	-	added	0	-	6-May	Excellent
802	5-May	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	P. Tap near Krishna Cottege ShivPuri	-	added	0	-	7-May	Excellent
803			2	Shiv Puri Tank	-	added	0	-	7-May	Excellent
804			3	P. Tap Shiv Puri	-	added	0	-	7-May	Excellent
805			4	P Tap Joshi Niwas Shiv Puri	-	added	0	-	7-May	Excellent
806			5	Sanjauli Reservoir Outlet	-	added	0	-	7-May	Excellent
807			6	Kasumpti Reservoir	-	added	0	-	7-May	Excellent