

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	Final report (72Hrs)	Reported on	Result
1213	9-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Water Tank tawri Totu	-	added	0	-	11-Jul	Excellent
1214			2	Public tap Vad building , new Totu	-	added	0	-	11-Jul	Excellent
1215			3	Public tap near Gupta PCO totu bazaar	-	added	0	-	11-Jul	Excellent
1216			4	water tank Yadghar totu	-	added	0	-	11-Jul	Excellent
1218			6	Tubewell 2 (U.V) Plant treated water Ashwani khad	-	nil	0	-	11-Jul	Excellent
1219			7	Water tank, kasumpti outlet	-	added	MPN=5	citrobacter koserii (5/100ml)	11-Jul	suspicious
1220			8	Sanjauli Reservoir Outlet	-	added	MPN=6	citrobacter koserii(6/100ml)	11-Jul	suspicious
1221	10-Jul	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	Public tap near Block A ,Vikas nagar	-	added		-	12-Jul	Excellent
1222			2	Kasumpti near SDA Complex tank	-	added		-	12-Jul	Excellent
1223			3	Public tap below Axis bank SDA Complex	-	added		-	12-Jul	Excellent
1224			4	Vikas nagar near Block C- 41 tank	-	added		-	12-Jul	Excellent
1226			6	tubewell no 2 , ashwani khad (u.v) treated water	-	nil	MPN = 180	-	12-Jul	unsatisfactory
1227			7	kasumpti reserivior	-	added		-	12-Jul	Excellent
1228			8	sanjauli reserivior	-	added		-	12-Jul	Excellent