

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	Final report (72Hrs)	Reported on	Result
1761	9/Aug	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	public tap, police post, Lakkar bazar	-	added	MPN=2		11 aug.	satisfactory
1762			2	Sanjauli reservoir	-	added	MPN=3		11 aug.	satisfactory
1763			3	Dhingoo Mandir Tank(lower)	-	added			11 aug.	excellent
1764			4	Dhingoo Mandir Tank(upper)	-	added	MPN=4	Citrobacter spp.	11 aug.	suspicious(Not fit for drinking)
1765			5	main supply from Dhingoo mandir tank(upper)	-	added	MPN=3		11 aug.	satisfactory
1766			6	Tubewell no 2(uv)Ashwani khad(untreated)	-	nil	MPN=180	Citrobacter koseri	11 aug.	Unsatisfactory
1767			7	Tubewell no 2(uv)Ashwani khad(treated)	-	nil	MPN=1		11 aug.	satisfactory
1768			8	Kasumpati reservoir		added			11 aug.	excellent
1769	9/Aug	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	Ridge tank shimla	-	added			11 aug.	Excellent
1770			2	mains field tank	-	added			11 aug.	Excellent
1771			3	bharari tank	-	added			11 aug.	Excellent
1772			4	dhali tank	-	added			11 aug.	Excellent
1773			5	tavi tank	-	added			11 aug.	Excellent
1774			6	knoll wood	-	added			11 aug.	Excellent
1775			7	jakhu tank	-	added			11 aug.	Excellent
1776			8	vikasnagar tank	-	added			11 aug.	Excellent
1777			9	handpump mashobra	-	nil			11 aug.	Excellent
1778			10	Bowari near mahanagar hotel			MPN=180+			unsatisfactory

1779			11	near dhali public tap	-	nil			11 aug.	Excellent
1780			12	G.S.S.S dhali public tap	-	nil	MPN=25		11 aug.	unsatisfactory
1781	10/Aug	Samples received	1	North	-	added			12/Aug	Excellent
1782			2	North Oak(OH) tank	-	added	MPN=5	Citrobacter koseri	13/Aug	suspicious(Not fit for drinking)
1783			3	Sanjauli reservoir	-	added			12/Aug	Excellent
1784			4	sanjauli tank inlet from Gumma	-	added	MPN=1		13/Aug	satisfactory
1785			5	Phase III tank, near block 6R7	-	added	MPN=1		13/Aug	satisfactory
1786			6	tubewell no 2(UV), Ashwani khad (untreated)	-	nil	MPN=180	E. coli (50/100 ml)	13/Aug	unsatisfactory
1787			7	tubewell no.2, Ashwani khad (treated)	-	nil			12/Aug	Excellent
1788			8	Kasumpti Reservoir	-	added			12/Aug	Excellent
1789	10/Aug	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	Ridge tank shimla	-	added			13/Aug	Excellent
1790			2	mains field tank	-	added			13/Aug	Excellent
1791			3	keleston tank	-	added			13/Aug	Excellent
1792			4	dhali tank	-	added			13/Aug	Excellent
1793			5	chakkar tank	-	added			13/Aug	Excellent
1794			6	phase 3 tank	-	added			13/Aug	Excellent
1795			7	handpump near public toilet lakkar bazar	-	nil	MPN=5		13/Aug	
1796			8	sargheen tank	-	added			13/Aug	Excellent
1797			9	bawari anji vikasnagar	-	nil	MPN=90		13/Aug	unsatisfactory
1798			10	bawari devnagar	-	nil	MPN=180+		13/Aug	unsatisfactory

1799			11	public distribution meter sector 6	-	nil			13/Aug	Excellent
1800			12	public distribution meter sector 7	-	nil	MPN=1		13/Aug	
1801	11/Aug	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	tara mata mandir tank bcs	-	added	MPN= 30		13/Aug	unsatisfactory
1802			2	mc office tap new shimla	-	added	MPN=5			in process
1803			3	new shimla sec 3 tank old	-	added			13/Aug	excellent
1804			4	new shimla se 3 tank new	-	added	MPN=11		13/Aug	unsatisfactory
1805			5	public tap nr mangla bhwan new shimla sec 3	-	added			13/Aug	excellent
1806			6	kasumpti reservior	-	added			13/Aug	excellent
1807			7	public tap sanjauli chowk	-	added			13/Aug	excellent
1808			8	sanjauli reservior	-	added			13/Aug	excellent
1809	11 aug.	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	ridge tank shimla	-	added			13/Aug	excellent
1810			2	mains field tank	-	added			13/Aug	excellent
1811			3	bharari tank	-	added			13/Aug	excellent
1812			4	dhali tank	-	added	MPN=2		13/Aug	

