

Water samples tested in Department of Microbiology IGMC, Shimla										
Lab Sr. no.	Date	Received through Email/Phone No.	Daily Sr No.	Source	Site	Na thiosulphate	PCC	Final report (72Hrs)	Reported on	Result
2399	14/Sep	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	sanjauli reservoir	-	Added			16/Sep	Excellent
2400			2	yadgar tank (totu)	-	Added	MPN=3		16/Sep	satisfactory
2401			3	IPH office tap totu	-	Added	MPN=10		16/Sep	suspicious(Not fit for drinking)
2402			4	hand pump annadale near bihari lal building	-	-	MPN=5		16/Sep	suspicious(Not fit for drinking)
2403			5	hand pump annadale chowk near ram mandir	-	-	MPN=3		16/Sep	satisfactory
2404			6	congress bhawan near lift	-	nil	MPN=180+		16/Sep	unsatisfactory
2405			7	kasumpti reservoir	-	Added	MPN=50		16/Sep	unsatisfactory
2406			8	p.tap ridge maidan	-	Added			16/Sep	Excellent
2407	14/Sep	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	Ridge tank shimla	-	Added			16/Sep	Excellent
2408			2	Mains field Tank	-	Added			16/Sep	Excellent
2409			3	bharari tank	-	Added			16/Sep	Excellent
2410			4	dhali tank	-	Added			16/Sep	Excellent
2411			5	tavi tank	-	Added			16/Sep	Excellent
2412			6	knolls wood tank	-	Added			16/Sep	Excellent
2413			7	jakhu Tank	-	Added			16/Sep	Excellent
2414			8	vikasnagar tank	-	Added			16/Sep	Excellent
2415			9	Upper chowk Khalini - public Tap	-	Added			16/Sep	Excellent
2416			10	Lower Khalini chowk - Public tap	-	Added	MPN=180		16/Sep	unsatisfactory
2417			11	forest Tank Near Kiryana Shope- Public Tap	-	Added	MPN=02		16/Sep	
2418			12	Devnagar Tibti bawari	-	nil	MPN=180+		16/Sep	unsatisfactory
2419			13	RDH, IGMC (inlet)	fresh	added	MPN=1			satisfactory
2420			14	RDH, IGMC (kitchen)	fresh	added				Excellent
2421	15/Sep	Samples received from Corporation Health Officer, Municipal Corporation Shimla, Shimla(H.P)	1	natural source near lalpani slaughter house	-	nil	MPN=180			unsatisfactory
2422			2	tara mata mandir tank BCS	-	Added	0			excellent
2423			3	phase 3 tank near block 6&7	-	Added	0			excellent
2424			4	Kasumpati Reservoir	-	Added	0			excellent

2425			5	lakar bazar Blessington girls school,MC supply	-	Added	0			excellent
2426			6	Lakkar bazar Blessington girls hostel,mess tap	-	Added	0			excellent
2427			7	public tap,Dhalli filter	-	Added	0			excellent
2428			8	Sanjauli reservoir	-	added	0			excellent
2429	15/Sep	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	ridge tank shimla	-	Added				excellent
2430			2	MAINS FIELD TANK	-	Added				excellent
2431			3	kaleston tank	-	Added				excellent
2432			4	public tap near keleston tank	-	Added				excellent
2433			5	chakkar tank	-	Added	MPN=180			unsatisfactory
2434			6	phase 3 tank	-	Added				excellent
2435			7	jakhu tank	-	Added				excellent
2436			8	sargheen tank	-	Added				excellent
2437			9	public tap panthaghathi near shiv mandir	-	Added	MPN=90			unsatisfactory
2438			10	bawari banmore	-	nil				excellent