

Lab Sr. no.	Date	Received through Email/Phone No	Daily Sr No.	Source	Sodium Thiosulphate	MPN	Final report (72Hrs)	FINAL REPORTING DATE	Result
4505	7/9/2019	Samples received from Assistant Engineer, Shimla Jal Prabandhan Nigam Ltd	1	KASUMPATI RESERVIR	added	MPN=0	thermotolerant E.coli not detected	9/9/2019	EXCELLENT
4506			2	TARA MATA MANDIR TANK (REPEAT)	added	MPN=0	thermotolerant E.coli not detected	9/9/2019	EXCELLENT
4507			3	P.TAP NEAR CHADDHA TRANSPORT BELOW BUS STAND	added	MPN=0	thermotolerant E.coli not detected	9/9/2019	EXCELLENT
4508			4	P.TAP NEAR GADDI KHANA	added	MPN=7	thermotolerant E.coli not detected	9/9/2019	ADV : REPEAT SAMPLE
4509			5	P.TAP NEAR COUNCILLOR HOUSE RULDUBHATTA	added	MPN=0	thermotolerant E.coli not detected	9/9/2019	EXCELLENT
4510			6	P.TAP NEAR SHYAM SINGH BUILDING RULDUBHATTA	added	MPN=3	thermotolerant E.coli not detected	9/9/2019	SATISFACTORY
4511			7	P.TAP NEAR SHIV COTTAGE RULDUBHATTA	added	MPN=5	thermotolerant E.coli not detected	9/9/2019	ADV : REPEAT SAMPLE
4512			8	SANJAULI RESERVOIR	added	MPN=3	thermotolerant E.coli not detected	9/9/2019	SATISFACTORY
4513	7/9/2019	Samples Received under Hepatitis Project Community Medicine IGMC Shimla	1	Ridge tank	added	MPN=0		9/9/2019	EXCELLENT
4514			2	mains field tank	added	MPN=3		9/9/2019	
4515			3	Bharari tank	added	MPN=0		9/9/2019	excellent
4516			4	Dhalli tank	added	MPN=2		9/9/2019	
4517			5	Pub-tap totu	added	MPN=10		9/9/2019	unsatisfactory
4518			6	Phase-3 tank	added	MPN=0		9/9/2019	excellent
4519			7	Jakhu tank ropeway	added	MPN=0		9/9/2019	excellent
4520			8	Sargeen tank	added	MPN=0		9/9/2019	excellent
4521			9	Pub-tap sargeen	added	MPN=1		9/9/2019	
4522			10	Pub-tap Police gumti Chotta Shimla	added	MPN=3		9/9/2019	
4523			11	Pub-tap near Apna Medical store Chotta Shimla	added	MPN=11		9/9/2019	Unsatisfactory
4524			12	Pub-tap chintpurni chowk khalini	added	MPN=1		9/9/2019	

4525	8/9/2019	Samples received from Assistant Engineer, Shimla Jal Prabandhan Nigam Ltd	1	KASUMPTI RESERVOIR	added	MPN=0	thermotolerant E.coli not detected	11/9/2019	EXCELLENT
4526			2	P. TAP NEAR KRISHNA HILL, ANNADALE	added	MPN=1	thermotolerant E.coli not detected	11/9/2019	SATISFACTORY
4527			3	SUPPLY NEAR SYLVERTON THAKUR BAG	added	MPN=0	thermotolerant E.coli not detected	11/9/2019	EXCELLENT
4528			4	P.TAP NEAR SHANTI KUNJ , ANNADALE	added	MPN=0	thermotolerant E.coli not detected	11/9/2019	EXCELLENT
4529			5	P.TAP NEAR DHOBIGHAT	added	MPN=0	thermotolerant E.coli not detected	11/9/2019	EXCELLENT
4530			6	P.TAP NEAR LAXMI NIWAS ANNADALE	added	MPN=0	thermotolerant E.coli not detected	11/9/2019	EXCELLENT
4531			7	TARAHALL TANK	added	MPN=0	thermotolerant E.coli not detected	11/9/2019	EXCELLENT
4532			8	SANJAULI RESERVOIR	added	MPN=0	thermotolerant E.coli not detected	11/9/2019	EXCELLENT
4533	9/9/2019	Samples received from Assistant Engineer, Shimla Jal Prabandhan Nigam Ltd	1	KASUMPATI RESERVOIR	added	MPN=0	thermotolerant E.coli not detected	12/9/2019	EXCELLENT
4534			2	KNOLLSWOOD TANK (REPEAT)	added	MPN=0	thermotolerant E.coli not detected	12/9/2019	EXCELLENT
4535			3	P.TAP NEAR KHALINI CHOWK (REPEAT)	added	MPN = 5	thermotolerant E.coli not detected	12/9/2019	SUSPICIOUS
4536			4	P.TAP NEAR BY PASS ROAD KHALINI (REPEAT)	added	MPN=1	thermotolerant E.coli not detected	12/9/2019	SATISFACTORY
4537			5	ENGINE GHAR TANK	added	MPN=10	thermotolerant E.coli not detected	12/9/2019	ADV : REPEAT SAMPLE
4538			6	P.TAP NEAR MEHTA PARKING	added	MPN=17	thermotolerant E.coli not detected	12/9/2019	ADV : REPEAT SAMPLE
4539			7	P.TAP NEAR GOEL APARTMENT DHINGU (REPEAT)	added	MPN = 2	thermotolerant E.coli not detected	12/9/2019	SATISFACTORY
4540			8	SANJAULI RESERVOIR	added	MPN=12	thermotolerant E.coli not detected	12/9/2019	Unsatisfactory