

RESULTS OF BACTERIOLOGICAL SAMPLES RECEIVED ON DATED 07-12-2020

Sr. No.	Collection Date	Lab. Code	Location of Sample taken	ANALYSIS RESULTS		Final Reporting Date
				Total Coliform MPN/100 ml	E.Coli MPN/100 ml	
1	07.12.2020	1441	Kasumpati Reservoir	<1.1	Not Required	10-12-20
2		1442	Jakhu tank near hanuman temple	<1.1	Not Required	10-12-20
3		1443	Mainsfield tank	<1.1	Not Required	10-12-20
4		1444	Knollswood tank	<1.1	Not Required	10-12-20
5		1445	P. tap near bharari tank	<1.1	Not Required	10-12-20
6		1446	P. tap near police colony bharari	<1.1	Not Required	10-12-20
7		1447	Supply near bhalla niwas	<1.1	Not Required	10-12-20
8		1448	P. Tap Near Police Ground Bharari	<1.1	Not Required	10-12-20
9		1449	Bharari tank	<1.1	Not Required	10-12-20
10		1450	Kleistein tank	<1.1	Not Required	10-12-20
11		1451	Sanjauli reservoir	<1.1	Not Required	10-12-20
12		1452	Giri inlet	<1.1	Not Required	10-12-20
13		1453	Gumma inlet	<1.1	Not Required	10-12-20
14		1454	Dhalli tank outlet	<1.1	Not Required	10-12-20
15		1455	P. Tap near Bhagwati Niwas Lakkar Bazar	<1.1	Not Required	10-12-20
16		1456	P. Tap Near Councillor House Ruldubhatta	<1.1	Not Required	10-12-20
17		1457	P. Tap Near Shiv Cottage Ruldubhatta	<1.1	Not Required	10-12-20
18		1458	P. tap near shyam singh cottage ruldubhatta	<1.1	Not Required	10-12-20
19		1459	P. tap near idgah ruldubhatta	<1.1	Not Required	10-12-20
20		1460	Tara Mata Mandir Tank	<1.1	Not Required	10-12-20