

DATED	LAB S.No.	RECEIVED FROM	DAILY S.No.		SODIUM THIOSULPHATE 333	FINAL REPORT (AFTER 72 HOURS)	FINAL REPORTING DATE	RESULT
07-10-20	3631	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		13/7/2020	Excellent
	3632		2	MAINSFIELD TANK	added		13/7/2020	Excellent
	3633		3	JAKHU TANK NEAR ROPEWAY	added		13/7/2020	Excellent
	3634		4	DHALLI CATCHMENT INLET	added		13/7/2020	Excellent
	3635		5	CHURAT AND JAGRITI INLET	added		13/7/2020	Excellent
	3636		6	DHALLI TANK OUTLET	added		13/7/2020	Excellent
	3637		7	PUBLIC TAP NEAR POLICE COLONY BHARARI	added		13/7/2020	Excellent
	3638		8	SUPPLY NEAR BHALLA NIWAS	added	thermotolerant E.coli not detected	13/7/2020	SATISFACTORY
	3639		9	PUBLIC TAP NEAR BHARARI TEMPLE	added		13/7/2020	Excellent
	3640		10	PUBLIC TAP NEAR POLICE GROUND BHARARI	added		13/7/2020	Excellent
	3641		11	BHARARI TANK	added		13/7/2020	Excellent
	3642		12	KLESTAN TANK	added		13/7/2020	Excellent
	3643		13	BHIMAKALI TANK	added	thermotolerant E.coli not detected	13/7/2020	Unsatisfactory
	3644	14	103 TANK	added	thermotolerant E.coli not detected	13/7/2020	Unsatisfactory	
	3645	15	TUTIKANDI TANK	added	thermotolerant E.coli not detected	13/7/2020	Unsatisfactory	
	3646	16	PHAGLI TANK	added		13/7/2020	Excellent	
	3647	17	RIDGE TANK OUTLET	added		13/7/2020	Excellent	
	3648	18	SANJAULI RESERVOIR	added		13/7/2020	Excellent	
	3649	19	GIRI INLET	added		13/7/2020	Excellent	
	3650	20	GUMMA INLET	added		13/7/2020	Excellent	
07-11-20	3651	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		14/7/2020	Excellent
	3652		2	MAINSFIELD TANK	added	thermotolerant E.coli not detected	14/7/2020	SAtisfactory
	3653		3	JAKHU TANK NEAR ROPEWAY	added		14/7/2020	Excellent

	3654		4	PUBLIC TAP NEAR EVA SALES CORPORATION GANJ BAZAR	added		14/7/2020	Excellent
	3655		5	PUBLIC TAP NEAR PURUSHARTHI BASTI	added		14/7/2020	Excellent
	3656		6	Public tap near Sabji mandi Lower bazar	added	thermotolerant E.coli not detected	14/7/2020	Suspicious
	3657		7	PUBLIC TAP NEAR KHADI BANDHAR MALL ROAD	added		14/7/2020	Excellent
	3658		8	PUBLIC TAP NEAR SAMSUNG STORE MALL ROAD	added	thermotolerant E.coli not detected	14/7/2020	SATisfactory
	3659		9	RIDGE TANK OUTLET	added		14/7/2020	Excellent
	3660		10	Fingask Tank No.1	added	thermotolerant E.coli not detected	14/7/2020	SATISFACTORY
	3661		11	Fingask Tank No.2	added	thermotolerant E.coli not detected	14/7/2020	SATISFACTORY
	3662		12	ADVANCE STUDY TANK	added	thermotolerant E.coli not detected	14/7/2020	SATISFACTORY
	3663		13	103 TANK	added	thermotolerant E.coli not detected	14/7/2020	Unsatisfactory
	3664		14	BHARARI TANK	added		14/7/2020	Excellent
	3665		15	SANJAULI RESERVOIR	added		14/7/2020	Excellent
	3666		16	GIRI INLET	added	thermotolerant E.coli not detected	14/7/2020	SATisfactory
	3667		17	GUMMA INLET	added		14/7/2020	Excellent
	3668		18	Dhalli Catchment inlet	added	thermotolerant E.coli not detected	14/7/2020	SATISFACTORY
	3669		19	Churat and Jagrati inlet	added		14/7/2020	Excellent
	3670		20	Dhalli tank outlet	added	thermotolerant E.coli not detected	14/7/2020	SATisfactory
07-12-20	3671	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		15/07/2020	Excellent
	3672		2	PHASE-II TANK NO.1	added		15/07/2020	Excellent
	3673		3	TARA MATA MANDIR TANK	added		15/07/2020	Excellent

	3674		4	MAINSFIELD TANK	added		15/07/2020	Excellent
	3675		5	JAKHU TANK NEAR ROPEWAY	added		15/07/2020	Excellent
	3676		6	RIDGE TANK OUTLET	added		15/07/2020	Excellent
	3677		7	SUPPLU NEAR SYLVERTON	added		15/07/2020	Excellent
	3678		8	P.TAP NEAR LAXMI NIWAS ANNADALE	added		15/07/2020	Excellent
	3679		9	TARA HALL TANK	added	thermotolerant E.coli not detected	15/07/2020	Unsatisfactory
	3680		10	ENGINE GHAR TANK(REPEAT)	added	thermotolerant E.coli not detected	15/07/2020	Satisfactory
	3681		11	P.TAP NEAR MEHTA PARKING, ENGINE GHAR(REPEAT)	added		15/07/2020	Excellent
	3682		12	BHIMAKALI TANK	added		15/07/2020	Excellent
	3683		13	TUTIKANDI TANK	added		15/07/2020	Excellent
	3684		14	SANJAULI RESERVOIR	added		15/07/2020	Excellent
	3685		15	GIRI INLET	added		15/07/2020	Excellent
	3686		16	GuMMA INLET	added		15/07/2020	Excellent
	3687		17	DHALLI CATCHMENT INLET	added		15/07/2020	Excellent
	3688		18	CHURAT JAGRATI INLET	added		15/07/2020	Excellent
	3689		19	DHALLI TANK OUTLET	added		15/07/2020	Excellent
	3690		20	KALYANI TANK CHARABRA	added		15/07/2020	Excellent
13/7/2020	3691	Samples received from A.E. , SJPN Ltd.	1	DHALLI CATCHMENT INLET	added		16/07/2020	Excellent
	3692		2	CHURAT AND JAGRITI INLET	added	thermotolerant E.coli not detected	16/07/2020	Unsatisfactory
	3693		3	DHALLI TANK OUTLET	added	thermotolerant E.coli not detected	16/07/2020	Unsatisfactory
	3694		4	TARA MATA MANDIR TANK	added		16/07/2020	Excellent
	3695		5	PHASE 3 TANK NO 1	added	thermotolerant E.coli not detected	16/07/2020	Satisfactory
	3696		6	KASUMPATI RESERVOIR	added		16/07/2020	Excellent
	3697		7	MAINSFIELD TANK	added	thermotolerant E.coli not detected	16/07/2020	satisfactory
	3698		8	JAKHU TANK NEAR ROPEWAY	added		16/07/2020	Excellent
	3699		9	ADVANCE STUDY TANK	added		16/07/2020	Excellent

	3700		10	PUBLIC TAP NEAR SUMMER HILL CHOWK	added		16/07/2020	Excellent
	3701		11	PUBLIC TAP NEAR RAJ DAIRY SUMMER HILL	added		16/07/2020	Excellent
	3702		12	SUMMER HILL BAJAR TANK	added	thermotolerant E.coli not detected	16/07/2020	Suspicious
	3703		13	PUBLIC TAP NEAR LOWER SUMMER HILL	added		16/07/2020	Excellent
	3704		14	CHAKKAR TANK	added		16/07/2020	Excellent
	3705		15	PHAGLI TANK	added	thermotolerant E.coli not detected	16/07/2020	satisfactory
	3706		16	RIDGE TANK OUTLET	added	thermotolerant E.coli not detected	16/07/2020	satisfactory
	3707		17	KLESTAN TANK	added		16/07/2020	Excellent
	3708		18	SANJAULI RESERVOIR	added		16/07/2020	Excellent
	3709		19	GIRI INLET	added	thermotolerant E.coli not detected	16/07/2020	satisfactory
	3710		20	GUMMA INLET	added	thermotolerant E.coli not detected	16/07/2020	satisfactory
14/7/2020	3711	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added	thermotolerant E.coli not detected	17/07/2020	Suspicious
	3712		2	PECE.3 TANK NO 1	added		17/07/2020	Excellent
	3713		3	TARA MATA MANDIR TANK	added		17/07/2020	Excellent
	3714		4	MAINSFIELD TANK	added		17/07/2020	Excellent
	3715		5	JAKHU TANK NEAR ROPEWAY	added		17/07/2020	Excellent
	3716		6	RIDGE TANK OUTLET	added		17/07/2020	Excellent
	3717		7	BHIMAKALI TANK	added	thermotolerant E.coli not detected	17/07/2020	SATISFACTORY
	3718		8	103 TANK	added		17/07/2020	Excellent
	3719		9	BHARARI TANK	added		17/07/2020	Excellent
	3720		10	HOUSING BOARD COLONY TANK 1	added		17/07/2020	Excellent
	3721		11	HOUSING BOARD COLONY TANK 2	added		17/07/2020	Excellent
	3722		12	SANJAULI RESERVOIR	added		17/07/2020	Excellent
	3723		13	GIRI INLET	added		17/07/2020	Excellent
	3724		14	GUMMA INLET	added		17/07/2020	Excellent

	3725		15	NORTHOAK UG	added		17/07/2020	Excellent
	3726		16	NORTHOAK OG	added		17/07/2020	Excellent
	3727		17	PUBLIC TAP NEAR LUXMI NARayan temple	added		17/07/2020	Excellent
	3728		18	DHALLI CATCHMENT INLET	added		17/07/2020	Excellent
	3729		19	CHURAT AND JAGRITI INLET	added		17/07/2020	Excellent
	3730		20	DHALLI TANK OUTLET	added		17/07/2020	Excellent
15/07/2020	3731	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		18/07/2020	Excellent
	3732		2	Phase III tank No. 1	added	thermotolerant E.coli not detected	18/07/2020	Satisfactory
	3733		3	Phase III tank No. 3	added	thermotolerant E.coli not detected	18/07/2020	Satisfactory
	3734		4	TARA MATA MANDIR TANK	added		18/07/2020	Excellent
	3735		5	Sector-1 Tank	added		18/07/2020	Excellent
	3736		6	Sector-4 tank	added	thermotolerant E.coli not detected	18/07/2020	Satisfactory
	3737		7	Sector-2 tank	added	thermotolerant E.coli not detected	18/07/2020	Satisfactory
	3738		8	Public tap near M.C. office New Shimla	added	thermotolerant E.coli not detected	18/07/2020	Satisfactory
	3739		9	MAINSFIELD TANK	added		18/07/2020	Excellent
	3740		10	JAKHU TANK NEAR ROPEWAY	added	thermotolerant E.coli not detected	18/07/2020	Satisfactory
	3741		11	RIDGE TANK OUTLET	added		18/07/2020	Excellent
	3742		12	TUTIKANDI TANK	added		18/07/2020	Excellent
	3743		13	ADVANCE STUDY TANK	added	thermotolerant E.coli not detected	18/07/2020	Satisfactory
	3744		14	KLESTAN TANK	added		18/07/2020	Excellent
	3745		15	Dhalli Catchment inlet	added		18/07/2020	Excellent
	3746		16	Churat and Jagrati inlet	added	thermotolerant E.coli not detected	18/07/2020	Satisfactory

	3747		17	Dhalli tank outlet	added	thermotolerant E.coli not detected	18/07/2020	SATISFACTORY
	3748		18	SANJAULI RESERVOIR	added		18/07/2020	Excellent
	3749		19	GIRI INLET	added		18/07/2020	Excellent
	3750		20	GuMMA INLET	added		18/07/2020	Excellent
16/7/2020	3751	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added	thermotolerant E.coli not detected	19/7/2020	SATISFACTORY
	3752		2	PHASE 3 TANK NO 1	added	thermotolerant E.coli not detected	19/7/2020	SATISFACTORY
	3753		3	TARA MATA MANDIR TANK	added	thermotolerant E.coli not detected	19/7/2020	SATISFACTORY
	3754		4	PUBLIC TAP NEAR BYPASS ROAD KHALINI	added	thermotolerant E.coli not detected	19/7/2020	SUSPICIOUS
	3755		5	PUBLIC TAP NEAR PANCHIATHA	added	thermotolerant E.coli not detected	19/7/2020	SATISFACTORY
	3756		6	Public tap near Kali mata mandir Bhagwati nagar	added	thermotolerant E.coli not detected	19/7/2020	SATISFACTORY
	3757		7	PUBLIC TAP NEAR KHALINI CHOWK	added	thermotolerant E.coli not detected	19/7/2020	SATISFACTORY
	3758		8	KNOLLSWOOD TANK	added	thermotolerant E.coli not detected	19/7/2020	SATISFACTORY
	3759		9	MAINSFIELD TANK	added		19/7/2020	Excellent
	3760		10	JAKHU TANK NEAR ROPEWAY	added	thermotolerant E.coli not detected	19/7/2020	SATISFACTORY
	3761		11	RIDGE TANK OUTLET	added	thermotolerant E.coli not detected	19/7/2020	SATISFACTORY
	3762		12	CHAKKAR TANK	added	thermotolerant E.coli not detected	19/7/2020	SUSPICIOUS
	3763		13	PHAGLI TANK	added	thermotolerant E.coli not detected	19/7/2020	SUSPICIOUS

	3764		14	BHARARI TANK	added	thermotolerant E.coli not detected	19/7/2020	SATISFACTORY
	3765		15	DHALLI CATCHMENT INLET	added		19/7/2020	Excellent
	3766		16	CHURAT AND JAGRITI INLET	added	thermotolerant E.coli not detected	19/7/2020	UNSATISFACTORY
	3767		17	DHALLI TANK OUTLET	added	thermotolerant E.coli not detected	19/7/2020	UNSATISFACTORY
	3768		18	SANJAULI RESERVOIR	added		19/7/2020	Excellent
	3769		19	GIRI INLET	added	thermotolerant E.coli not detected	19/7/2020	SATISFACTORY
	3770		20	GuMMA INLET	added	thermotolerant E.coli not detected	19/7/2020	SATISFACTORY