

DATED	LAB S.No.	RECEIVED FROM	DAILY S.No.	SODIUM THIOSULPHATE	FINAL REPORT (AFTER 72 HOURS)	FINAL REPORTING DATE	RESULT	
20/7/2020	3831	Samples received from A.E. , SJPN Ltd.	1	333	added	thermotolerant E.coli not detected	23/07/2020	SATISFACTORY
	3832		2		added	thermotolerant E.coli not detected	23/07/2020	SATISFACTORY
	3833		3		added	thermotolerant E.coli not detected	23/07/2020	UNSATISFACTORY
	3834		4		added	thermotolerant E.coli not detected	23/07/2020	SATISFACTORY
	3835		5		added		23/07/2020	Excellent
	3836		6		added		23/07/2020	Excellent
	3837		7		added	thermotolerant E.coli not detected	23/07/2020	SATISFACTORY
	3838		8		added	thermotolerant E.coli not detected	23/07/2020	SATISFACTORY
	3839		9		added		23/07/2020	Excellent
	3840		10		added		23/07/2020	Excellent
	3841		11		added		23/07/2020	Excellent
	3842		12		added		23/07/2020	Excellent
	3843		13		added		23/07/2020	Excellent
	3844		14		added	thermotolerant E.coli not detected	23/07/2020	SATISFACTORY
	3845		15		added		23/07/2020	Excellent
	3846		16		added		23/07/2020	Excellent
	3847		17		added		23/07/2020	Excellent
	3848		18		added		23/07/2020	Excellent
	3849		19		added		23/07/2020	Excellent
	3850		20		added		23/07/2020	Excellent
21/7/2020	3851	Samples received from A.E. , SJPN Ltd.	1		added		24/07/2020	Excellent
	3852		2		added		24/07/2020	Excellent
	3853		3		added	thermotolerant E.coli not detected	24/07/2020	Satisfactory
	3854		4		added		24/07/2020	Excellent
	3855		5		added		24/07/2020	Excellent
	3856		6		added		24/07/2020	Excellent
	3857		7		added		24/07/2020	Excellent
	3858		8		added		24/07/2020	Excellent
	3859		9		added		24/07/2020	Excellent
	3860		10		added		24/07/2020	Excellent
	3861		11		added		24/07/2020	Excellent
	3862		12		added		24/07/2020	Excellent
	3863		13		added		24/07/2020	Excellent
	3864		14		added		24/07/2020	Excellent
	3865		15		added		24/07/2020	Excellent
	3866		16		added	thermotolerant E.coli not detected	24/07/2020	Satisfactory
	3867		17		added		24/07/2020	Excellent
	3868		18		added		24/07/2020	Excellent

	3869		19	TUTIKANDI TANK	added	thermotolerant E.coli not detected	24/07/2020	Satisfactory
	3870		20	RIDGE TANK OUTLET	added		24/07/2020	Excellent
22/07/2020	3871	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		25/7/2020	Excellent
	3872		2	Phase III tank No. 1	added	thermotolerant E.coli not detected	25/7/2020	SATISFACTORY
	3873		3	TARA MATA MANDIR TANK	added		25/7/2020	Excellent
	3874		4	PUBLIC TAP NEAR MC OFFICE NEW SHIMLA	added		25/7/2020	Excellent
	3875		5	SECTOR 3 NEW TANK	added		25/7/2020	Excellent
	3876		6	Public tap near Mangla BHAWAN New Shimla	added		25/7/2020	Excellent
	3877		7	PUBLIC TAP NEAR KRANTI CHOWK	added		25/7/2020	Excellent
	3878		8	Sector-3 old tank outlet	added		25/7/2020	Excellent
	3879		9	MAINSFIELD TANK	added		25/7/2020	Excellent
	3880		10	Jakhu tank near Ropeway	added		25/7/2020	Excellent
	3881		11	RIDGE TANK OUTLET	added		25/7/2020	Excellent
	3882		12	PHAGLI TANK	added		25/7/2020	Excellent
	3883		13	ADVANCE STUDY TANK	added		25/7/2020	Excellent
	3884		14	KLESTAN TANK	added	thermotolerant E.coli not detected	25/7/2020	Excellent
	3885		15	SANJAULI RESERVOIR	added	thermotolerant E.coli not detected	25/7/2020	SATISFACTORY
	3886		16	GIRI INLET	added		25/7/2020	Excellent
	3887		17	GUMMA INLET	added		25/7/2020	Excellent
	3888		18	Dhali catchment inlet	added	thermotolerant E.coli not detected	25/7/2020	UNSATISFACTORY
	3889		19	Churat and Jagrati inlet	added		25/7/2020	Excellent
	3890		20	Dhali tank outlet	added		25/7/2020	Excellent
23/7/2020	3891	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		26/7/2020	Excellent
	3892		2	PHASE 3 TANK NO 1	added		26/7/2020	Excellent
	3893		3	TARA MATA MANDIR TANK	added	thermotolerant E.coli not detected	26/7/2020	SATISFACTORY
	3894		4	PUBLIC TAP NEAR A1 BLOCK VIKAS NAGAR	added	thermotolerant E.coli not detected	26/7/2020	SUSPICIOUS
	3895		5	SDA KASUMPTI TANK	added		26/7/2020	Excellent
	3896		6	Public tap near Durga cottage S.D.A. COMPLEX	added	thermotolerant E.coli not detected	26/7/2020	UNSATISFACTORY
	3897		7	KNOLLSWOOD TANK	added	thermotolerant E.coli not detected	26/7/2020	SUSPICIOUS
	3898		8	MAINSFIELD TANK	added		26/7/2020	Excellent
	3899		9	JAKHU TANK NEAR ROPEWAY	added		26/7/2020	Excellent
	3900		10	RIDGE TANK OUTLET	added		26/7/2020	Excellent
	3901		11	BHIMAKALI TANK	added		26/7/2020	Excellent
	3902		12	103 TANK	added		26/7/2020	Excellent
	3903		13	PUBLIC TAP NEAR KHALINI CHOWK	added	thermotolerant E.coli not detected	26/7/2020	SATISFACTORY
	3904		14	PUBLIC TAP NEAR BYPASS ROAD KHALINI	added		26/7/2020	Excellent
	3905		15	SANJAULI RESERVOIR	added	thermotolerant E.coli not detected	26/7/2020	SATISFACTORY

	3906		16	GIRI INLET	added	thermotolerant E.coli not detected	26/7/2020	Satisfactory
	3907		17	GUMMA INLET	added		26/7/2020	Excellent
	3908		18	DHALLI CATCHMENT INLET	added	thermotolerant E.coli not detected	26/7/2020	Satisfactory
	3909		19	CHURAT AND JAGRITI INLET	added	thermotolerant E.coli not detected	26/7/2020	Satisfactory
	3910		20	DHALLI TANK OUTLET	added		26/7/2020	Excellent
24/7/2020	3911	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		27/07/2020	Excellent
	3912		2	Phase III tank No.1	added		27/07/2020	Excellent
	3913		3	TARA MATA MANDIR TANK	added		27/07/2020	Excellent
	3914		4	MAINSFIELD TANK	added		27/07/2020	Excellent
	3915		5	Jakhu tank near ropeway	added		27/07/2020	Excellent
	3916		6	RIDGE TANK OUTLET	added		27/07/2020	Excellent
	3917		7	TUTIKANDI TANK	added		27/07/2020	Excellent
	3918		8	PUBLIC TAP NEAR POLICE GROUND BHARARI	added		27/07/2020	Excellent
	3919		9	PUBLIC TAP NEAR BHARARI TEMPLE	added	thermotolerant E.coli not detected	27/07/2020	Satisfactory
	3920		10	PUBLIC TAP NEAR POLICE COLONY BHARARI	added		27/07/2020	Excellent
	3921		11	Public tap near Bhalla niwas Bharari	added		27/07/2020	Excellent
	3922		12	KLESTAN TANK	added		27/07/2020	Excellent
	3923		13	BHARARI TANK	added	thermotolerant E.coli not detected	27/07/2020	Satisfactory
	3924		14	CHAKKAR TANK	added		27/07/2020	Excellent
	3925		15	SANJAULI RESERVOIR	added		27/07/2020	Excellent
	3926		16	GIRI INLET	added		27/07/2020	Excellent
	3927		17	GUMMA INLET	added		27/07/2020	Excellent
	3928		18	DHALLI CATCHMENT INLET	added	thermotolerant E.coli not detected	27/07/2020	Satisfactory
	3929		19	CHURAT AND JAGRITI INLET	added		27/07/2020	Excellent
	3930		20	DHALLI TANK OUTLET	added	thermotolerant E.coli not detected	27/07/2020	Satisfactory
25/7/2020	3931	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added	thermotolerant E.coli not detected	28/07/2020	SATISFACTORY
	3932		2	PHASE 3 TANK NO 1	added	thermotolerant E.coli not detected	28/07/2020	SATISFACTORY
	3933		3	TARA MATA MANDIR TANK	added	thermotolerant E.coli not detected	28/07/2020	SATISFACTORY
	3934		4	MAINSFIELD TANK	added	thermotolerant E.coli not detected	28/07/2020	SATISFACTORY
	3935		5	JAKHU TANK NEAR ROPEWAY	added		28/07/2020	Excellent
	3936		6	RIDGE TANK OUTLET	added	thermotolerant E.coli not detected	28/07/2020	SATISFACTORY
	3937		7	SUPPLY NEAR 18 FAMILY BIOLUGANJ	added	thermotolerant E.coli not detected	28/07/2020	SUSPICIOUS
	3938		8	KAMNADEVI TANK	added	thermotolerant E.coli not detected	28/07/2020	SATISFACTORY
	3939		9	PUBLIC TAP NEAR LOWER SUMMER HILL	added		28/07/2020	Excellent
	3940		10	PUBLIC TAP NEAR RAJ DIARY SUMMER HILL	added	thermotolerant E.coli not detected	28/07/2020	SATISFACTORY

	3941		11	PUBLIC TAP NEAR SUMMER HILL CHOWK	added		28/07/2020	Excellent
	3942		12	SUMMER HILL BAJAR TANK	added	thermotolerant E.coli not detected	28/07/2020	SATISFACTORY
	3943		13	ADVANCE STUDY TANK	added	thermotolerant E.coli not detected	28/07/2020	SUSPICIOUS
	3944		14	BHARARI TANK	added	thermotolerant E.coli not detected	28/07/2020	SATISFACTORY
	3945		15	SANJAULI RESERVOIR	added		28/07/2020	Excellent
	3946		16	GIRI INLET	added		28/07/2020	Excellent
	3947		17	GuMMA INLET	added		28/07/2020	Excellent
	3948		18	DHALLI CATCHMENT INLET	added		28/07/2020	Excellent
	3949		19	CHURAT AND JAGRITI INLET	added		28/07/2020	Excellent
	3950		20	DHALLI TANK OUTLET	added		28/07/2020	Excellent
26/7/2020	3951	Samples received from A.E. , SJPN Ltd.	1	KASUMPATI RESERVOIR	added		29/07/2020	Excellent
	3952		2	PHASE 3 TANK NO 1	added		29/07/2020	Excellent
	3953		3	TARA MATA MANDIR TANK	added		29/07/2020	Excellent
	3954		4	MAINSFIELD TANK	added		29/07/2020	Excellent
	3955		5	Jakhu tank near Ropeway	added		29/07/2020	Excellent
	3956		6	RIDGE TANK OUTLET	added		29/07/2020	Excellent
	3957		7	PUBLIC TAP NEAR DHOBI GHAT ANNADALE	added		29/07/2020	Excellent
	3958		8	PUBLIC TAP NEAR LAXMI NIWAS	added		29/07/2020	Excellent
	3959		9	SUPPLY NEAR SYLVERTON, TAHKUR BAGH	added		29/07/2020	Excellent
	3960		10	PUBLIC TAP NEAR KRISHNA HILL	added		29/07/2020	Excellent
	3961		11	TARA HALL TANK	added	thermotolerant E.coli not detected	29/07/2020	Satisfactory
	3962		12	BHIMAKALI TANK	added	thermotolerant E.coli not detected	29/07/2020	Satisfactory
	3963		13	TUTIKANDI TANK	added		29/07/2020	Excellent
	3964		14	KLESTAN TANK	added		29/07/2020	Excellent
	3965		15	GUMMA INLET	added		29/07/2020	Excellent
	3966		16	SANJAULI RESERVOIR	added		29/07/2020	Excellent
	3967		17	DHALLI CATCHMENT INLET	added		29/07/2020	Excellent
	3968		18	CHURAT AND JAGRITI INLET	added		29/07/2020	Excellent
	3969		19	DHALLI TANK OUTLET	added		29/07/2020	Excellent
	3970		20	KALYANI TANK CHARABRA	added		29/07/2020	Excellent
27/07/2020	3971	Samples received from A.E. , SJPN Ltd.	1	KASUMPTI RESERVOIR	added		30/7/2020	Excellent
	3972		2	Public tap near Durga cottage SDA complex	added	thermotolerant E.coli not detected	30/7/2020	SUSPICIOUS
	3973		3	MAINSFIELD TANK	added	thermotolerant E.coli not detected	30/7/2020	SATisfactory
	3974		4	JAKHU TANK NEAR ROPEWAY	added	thermotolerant E.coli not detected	30/7/2020	UNSATISFACTORY
	3975		5	Public tap near Goel Apartment Dhingu	added	thermotolerant E.coli not detected	30/7/2020	SATisfactory
	3976		6	DHINGU MANDIR TANK	added		30/7/2020	Excellent
	3977		7	Dhali catchment inlet	added	thermotolerant E.coli not detected	30/7/2020	SATisfactory
	3978		8	Churat and Jagrati inlet	added	thermotolerant E.coli not detected	30/7/2020	SATisfactory

	3979		9 Dhalli tank outlet	added	thermotolerant E.coli not detected	30/7/2020	SATISFACTORY
	3980		10 Public tap near Luxmi Narayan temple sanjauli	added	thermotolerant E.coli not detected	30/7/2020	SUSPICIOUS
	3981		11 PUBLIC TAP NEAR OLD POLICE THANA SANJAULI	added	thermotolerant E.coli not detected	30/7/2020	SATISFACTORY
	3982		12 NORTH OAK U.G. TANK	added	thermotolerant E.coli not detected	30/7/2020	SATISFACTORY
	3983		13 NORTH OAK O.H. TANK	added	thermotolerant E.coli not detected	30/7/2020	SATISFACTORY
	3984		14 GIRI INLET	added	thermotolerant E.coli not detected	30/7/2020	SATISFACTORY
	3985		15 GUMMA INLET	added	thermotolerant E.coli not detected	30/7/2020	UNSATISFACTORY
	3986		16 SANJAULI RESERVOIR	added	thermotolerant E.coli not detected	30/7/2020	SATISFACTORY
	3987		17 RIDGE TANK OUTLET	added	thermotolerant E.coli not detected	30/7/2020	SATISFACTORY
	3988		18 TUTIKANDI TANK	added	thermotolerant E.coli not detected	30/7/2020	SATISFACTORY
	3989		19 CHAKKAR TANK	added	thermotolerant E.coli not detected	30/7/2020	SUSPICIOUS
	3990		20 BHARARI TANK	added	thermotolerant E.coli not detected	30/7/2020	SATISFACTORY
28/07/2020	3991	Samples received from A.E. , SJPN Ltd.	1 KASUMPATI RESERVOIR	added		31/07/2020	Excellent
	3992		2 PHASE 3 TANK NO 1	added		31/07/2020	Excellent
	3993		3 PHASE 3 TANK NO 3	added		31/07/2020	Excellent
	3994		4 TARA MATA MANDIR TANK	added		31/07/2020	Excellent
	3995		5 PUBLIC TAP NEAR MC OFFICE NEW SHIMLA	added	thermotolerant E.coli not detected	31/07/2020	Satisfactory
	3996		6 SECTOR 4 TANK NEW SHIMLA	added		31/07/2020	Excellent
	3997		7 SECTOR 2 TANK NEW SHIMLA	added		31/07/2020	Excellent
	3998		8 SECTOR 1 TANK NEW SHIMLA	added		31/07/2020	Excellent
	3999		9 MAINSFIELD TANK	added		31/07/2020	Excellent
	4000		10 Jakhu tank near ropeway	added		31/07/2020	Excellent
	4001		11 RIDGE TANK OUTLET	added		31/07/2020	Excellent
	4002		12 ADVANCE STUDY TANK	added		31/07/2020	Excellent
	4003		13 PHAGLI TANK	added		31/07/2020	Excellent
	4004		14 KLESTAN TANK	added		31/07/2020	Excellent
	4005		15 SANJAULI RESERVOIR	added	thermotolerant E.coli not detected	31/07/2020	Satisfactory
	4006		16 GIRI INLET	added		31/07/2020	Excellent
	4007		17 GUMMA INLET	added		31/07/2020	Excellent
	4008		18 DHALLI CATCHMENT INLET	added		31/07/2020	Excellent
	4009		19 CHURAT AND JAGRITI INLET	added		31/07/2020	Excellent
	4010		20 DHALLI TANK OUTLET	added		31/07/2020	Excellent